




How to Install Disassembling Die of MSK-110 Crimper

1. Please first unscrew the screws (indicated in the yellow circle) and then take the upper and lower die off.



2. Well position the upper disassembling die and tighten the screw at the center of the top.



3. Well position the lower die base on the working stage and tighten the hex-screws.

