



Realtime Angle/AD:

+ 20- 7- 0

11

Max. Angle/AD:

+19-38-42

45

Control List:

AUTO

Rev:

Number:1


Ok

Deblug COM Open

Export Record:

Export All Data

Save Data



Order	Angle	FWHM	Scan	Time
Sc00X01	19-38-42	00-8	38-	01:48

A. Error ±0 / C.Angle: 19-38-42

Cancel

Save Data List

Order	Angle	Side	Scan	Time
-------	-------	------	------	------

A. deviation: Center angle:

Scan Range:

- 8'
- 10'
- 12'
- 14'
- 16'
- 18'
- 20'
- 22'
- 24'
- 26'
- 28'
- 30'
- 32'
- 40'
- 50'
- 1-
- 1.5-
- 2-
- 3-