

Raw Materials Impurity data for Cu single crystal

Cu	$\geq 99.999\%$
Pb	0.0002%
Ni	0.00005%
Zn	0.0002%
Fe	0.0001%
Mn	0.00005%
Sn	0.00005%
Bi	0.0001%
Mg	0.0001%
Ag	0.0001%
As	0.00005%